

ANNUAL SURVEYS.

28498

No. 133 Survey held at London Date Aug 2nd to 7th 1867.
 on the Ship "Peereps" Master R. Gilmouth
 Tonnage 777 Built at Sunderland When built 1859 (11 mo)
 By whom built Doxford Owners Merch^t. Sh. Co.
 Port belonging to London Destined Voyage Ceylon
 If Surveyed Afloat or in Dry Dock Canal dry Dock, and East India Dock.

Last Survey, No. 26707 Port of London Classed 10.A.1 (7.66)

The present Condition of the

Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder Ha good
 Copper and Y.M. When put on 1866

Windlass and Capstan
 Pumps 2
 Boats 4
 Masts, Yards, &c. good
 Sails
 Anchors No. of 3 B. 1 S. 1 H.
 Cables
 Hawser and Warps
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Sighted bottom the yellow metal patched and payed with Peacock patent paint, greater part of timbers lifted and beiling bc in hold scraped bright. She is now in good and efficient condition and fit in my opinion to remain as Classed 10.A.1.
 Committee's Minute 13 August 1867

Character assigned

10.A.1 W.B.

Joseph Keew.
 Certificate (if required)

No. 414 Survey held at London Date Aug 2nd to 5th 12th 1867.
 on the Ship "Colgrain" Master H. Hoard
 Tonnage 583 Built at Cochin When built 1853
 By whom built Owners Merch^t. Sh. Co.
 Port belonging to London Destined Voyage not fixed
 If Surveyed Afloat or in Dry Dock Canal dry Dock, and East India Dock.

Last Survey, No. 5088 Port of Lydal Classed 12.A.1. (5.66)
marked I.B. Cont 65. 4 yrs.

The present Condition of the

Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder Ha good
 Copper and Y.M. When put on 1866

Windlass and Capstan
 Pumps 2
 Boats 4
 Masts, Yards, &c. good
 Sails
 Anchors No. of 3 B. 1 S. 1 H.
 Cables
 Hawser and Warps
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

She is now in good and efficient condition and fit in my opinion to remain Classed .A.1
 Committee's Minute 13 August 1867

Character assigned

Cont^d 4.A.1 W.B.

Joseph Keew.
P.T. Over
 Certificate (if required).

28498 Lons.

Ship "Colgrain". 583 tons.

Sighted bottom Yellow Metal patched, and payed
with Peacocks patent paint

See London Report No 28813. Viz.
the middle line bottom are of Yellow Metal and the
whole of the doubling fastened with the same
material.

I therefore beg respectfully to recommend
that in accordance with Sec 70. the Mark II. II
be expunged from the Register Book.

Joseph Keen.



© 2021

Lloyd's Register
Foundation