

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 187 Survey held at London Date Aug 16 to Sep 5 1867  
on the Ship "Marchioness of Londonderry" H. H. Hall  
Tonnage 809 Built at Newcastle When built 1857  
By whom built Marshall Owners Marshall  
Port belonging to London Destined Voyage Calcutta  
If Surveyed Afloat or in Dry Dock Under Dry Dock & East India Dock

Last Survey, No. 26761 Port London Classed 13 A.S.  
REPAIRS now done Cont 64.9 yrs

The bottom caulked and re-sheathed with Yellow Metal on Felt -  
Eleven diagonal strap bolts renewed with Yellow Metal -

Present Condition of the

Decks	<u>good</u>	Treenails	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways		Breasthooks and Stenson		Pumps	<u>where</u>
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	<u>where</u>	Masts, Yards, &c.	<u>seen</u>
Lower Deck Beams & Fastenings	<u>where</u>	Ditto Ditto at other places		Condition, how ascertained	<u>by observation from the deck</u>
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves	<u>seen</u>	Anchors No. of <u>3 BLS 2K</u>	<u>good</u>
Topsides	<u>seen</u>	Ceiling		Cables	<u>where</u>
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter	<u>caulked</u>	Copper <u>T &amp; M</u> When put on <u>now</u>		Standing & Running Rigging	<u>seen</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>				

She is now in good condition fit in our opinion to remain as classed

The Amount of Fee.....£ - : - : is received by me,  
Special..... 1 : 1 :  
Certificate (if required) : 5 :  
Committee's Minute 13th September 1867  
Character assigned Cont 9 A.S.

A.S.  
B. W. Wainwright  
Lloyd's Register Foundation