

## ANNUAL SURVEYS.

28592

No.

Survey held at

London

Date Aug 16 to Sep 11 1867

on the Brig "Alligator"

Master G. Dale

Tonnage 207

Built at

Spawick

When built 1857

By whom built

Owners A Swanzy

Port belonging to

London

Destined Voyage

West coast of Africa

If Surveyed Afloat or in Dry Dock

Union Dry Dock &amp; West India Dock

Last Survey, No.

25659

Port of

Hon.

Classed

13A.1.

The present Condition of the

Decks caulked

Waterways caulked

Comings caulked

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers caulked

Sheerstrakes caulked

Topsides caulked

Wales caulked

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper FLYM

When put on

1865

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c. Masts new

Sails

Anchors No. of 3 B. S. 1 K

Cables

Hawsers and Warps

Standing &amp; Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

now done, The bottom sighted and the yellow metal patched, caulked from yellow metal line over to yellow metal line - The fore and main masts new - and a 3 bone anchor now supplied and the testing certificate produced, signed by Andrew Jack of Lloyd's Cambrian & A.P.T. Coy. Jan 7<sup>th</sup> 1867. 71.3.24 Tested to 9" 9.1. She is now where seen in good condition, fit in my opinion to remain as classed 13A.1.

Committee's Minute

13<sup>th</sup> September 1867

Character assigned

13A.1

Certificate (if required)

No.

Survey held at

London

Date Sep. 3 &amp; 4 1867

on the Bk. "Prinnee"

Master Ochultree

Tonnage 395

Built at

Sunderland

When built

1861

By whom built

Owners

Hall Bks.

Port belonging to

London

Destined Voyage

Cape of Good Hope

If Surveyed Afloat or in Dry Dock

Ratcliff Dry Dock

Last Survey, No.

10109

Port of

Newcastle

Classed

10A.1.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper FLYM

When put on

1864

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Sails

Anchors No. of 3 B. S. 2 K.

Cables

Hawsers and Warps

Standing &amp; Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

now done, The bottom sighted and the yellow metal patched, She is now where seen in good condition, and fit in my opinion to remain as classed 10A.1.

Committee's Minute

13<sup>th</sup> September 1867

Character assigned

10A.1

Certificate (if required)

LON652-0291