

Annual.

REPORT of SURVEY for REPAIRS.

28650

No. in Reg. Book. **No.** 369 Survey held at London Date Aug 28th to Sept 24th 1867
 on the Ship "Marlborough" Master J Purchase
 Tonnage 1402 Built at Newcastle When built 1846
 By whom built Smith Owners Smith and Co
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Green Up dry S^E and East India S^E

Last Survey, No. 28211 Port London Classed 12 A. 1 (Rest bl. 8th)
 REPAIRS None done.

Sighted bottom, the yellow metal patched, caulked the butts of topsides and overhauled the upper deck &c

Renewed the bowsprit with yellow pine the fore and main topsail yards with Red pine, also the gaff with the same material.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>2 Main S. 2 Fore</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>5</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>in pⁿ and engine</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 1 S. 1 K</u>
Topsides	Ceiling	Cables
Wales	Rudder <u>As good</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>Y. Mon</u> When put on <u>1866</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u>	

She is now in good and efficient condition, and fit in my opinion to remain as Classed 12 A. 1.
 Joseph Keen.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 1st October 18 67

Character assigned Rest. 8 A 1



© 2021

Lloyd's Register Foundation

LON652-0332