

REPORT of SURVEY for REPAIRS.

28674

No. in Reg. Book. **No.** 19 Survey held at London Date 25th October 18 67
 on the Brig "Agnes" Master Dollard
 Tonnage 177 Built at Barnstaple When built 1858
 By whom built _____ Owners W. Sparke
 Port belonging to London Destined Voyage St. Johns - Newfoundland
 If Surveyed Afloat or in Dry Dock in dry dock

Last Survey, No. 26925 Port London Classed 13 A 1
 7/65

REPAIRS

Now done:- Bottom sighted and the Yellow metal sheathing patched. - Renewed the Bolts in the upper Pintle and Brace to the Rudder. -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good where seen.</u>	Breasthooks and Stemson	Pumps <u>Two</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>Two</u> } <u>Good where seen.</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>Good</u>	Ditto Ditto at other places	Condition, how ascertained <u>By inquiry & observation</u>
Planksheers	Keelsons	Sails
Sheerstrakes } <u>Good where seen.</u>	Clamps and Shelves	Anchors No. of <u>3 B. 1 S. 2 R.</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>14 Gal.</u> When put on <u>1865</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u>	

She is in good and efficient condition, and fit, in my opinion, to remain classed: A 1.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 8th October 18 67

Character assigned 13 A 1



© 2021

Lloyd's Register Foundation

LN652-0356