

ANNUAL SURVEYS.

28715

No. 871 Survey held at London Date Sept 27th to Oct 21st 1867.
 on the Ship "Copenhagen" Master W. Lowie
 Tonnage 816 Built at India When built 1855
 By whom built _____ Owners J. H. Allan
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Lincoln Dry Dock & East India Dock

Last Survey, No. 27512 Port of London Classed 13 A. 1
 66

The present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats <u>five</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto ditto at other places	} <u>where</u>	Sails	} <u>where</u>
Planksheers		Keelsons		Anchors No. of <u>3 B. 1 S. 2 C.</u>	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper <u>YM</u> When put on <u>6/7</u>			

General Observations and Opinion, Now done, the bottom sighted and the yellow metal patched and a new main topmast fitted. She is now where seen in good condition fit in my opinion to remain as classed 13 A. 1
 Committee's Minute 25th October 1867
 Character assigned 13 A. 1 W.A.S.
J. H. Lowie
 Certificate (if required)

No. 913 Survey held at London Date Oct 9th to 19th 1867.
 on the Brig "Susan Bayley" Master Franklin
 Tonnage 158 Built at Swanwick When built 1853
 By whom built _____ Owners Banner Bros.
 Port belonging to London Destined Voyage West coast of Africa
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock & West India Dock

Last Survey, No. 27885 Port of London Classed 13 A. 1
 Cont 66. 4. 66

The present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto ditto at other places	} <u>where</u>	Sails	} <u>where</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper <u>on felt</u> When put on <u>1866</u>			

General Observations and Opinion, Now done, the bottom sighted and the yellow metal patched, She is now where seen in good condition fit in my opinion to remain as classed 13 A. 1
 Committee's Minute 25th October 1867
 Character assigned Cont 14 A. 1 W.A.S.
J. H. Lowie
 Certificate (if required)