

ANNUAL SURVEYS.

28727

No. 812 on the *Bg "Eudora"* Survey held at *London* Date *Oct 2nd to Oct 26th 1867*
 Tonnage *248* Built at *P. E. Isle* Master *Peake*
 By whom built *Hayden* Owners *Peake Bros*
 Port belonging to *P. E. Isle* Destined Voyage *Union Dry Dock & West India Dock*
 If Surveyed Afloat or in Dry Dock

Last Survey, No. *633* Port of *P. E. Island* Classed *7A* *66*

The present Condition of the

Decks	} <i>good</i>	Treenails	} <i>good</i>	Windlass and Capstan
Waterways		Breasthooks and Stenson		Pumps
Comings		Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.
Lower Deck Beams & Fastenings	} <i>where</i>	Do Do at other places	} <i>where</i>	Sails
Planksheers		Keelsons		Anchors No. of
Sheerstrakes		Clamps and Shelves		Cables
Topsides		Ceiling		Hawsers and Warps
Wales	} <i>seen</i>	Rudder	} <i>seen</i>	Standing & Running Rigging
Plank (Bottom) and Counter		Copper		When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *good where seen*

Now done, the bottom sighted and three 3/8 holes in the bottom plugged. She is now where seen in good condition fit in my opinion to remain as classed 7A. The owners do not wish her surveyed for the Fig. but present.

Committee's Minute *29th Oct 1867*

Character assigned *7A* *WMS*

Certificate (if required)

No. 29 on the *BK "Naparima"* Survey held at *London* Date *Oct 18 67*
 Tonnage *356* Built at *Bristol* Master *Allen*
 By whom built *London* Owners *Scrutton &*
 Port belonging to *London* Destined Voyage *West Indies*
 If Surveyed Afloat or in Dry Dock *Union Dry Dock & West India Dock*

Last Survey, No. *25612* Port of *London* Classed *13A.1* *63*

The present Condition of the

Decks	} <i>good</i>	Treenails	} <i>good</i>	Windlass and Capstan
Waterways		Breasthooks and Stenson		Pumps
Comings		Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.
Lower Deck Beams & Fastenings	} <i>where</i>	Do Do at other places	} <i>where</i>	Sails
Planksheers		Keelsons		Anchors No. of <i>3 B S M</i>
Sheerstrakes		Clamps and Shelves		Cables
Topsides		Ceiling		Hawsers and Warps
Wales	} <i>seen</i>	Rudder	} <i>seen</i>	Standing & Running Rigging
Plank (Bottom) and Counter		Copper <i>T. & Y.M.</i>		When put on <i>1863</i>

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *good where seen*

Now done, the bottom sighted and the yellow metal patched. She is now where seen in good condition, fit in my opinion to remain as classed 13A.1.

Committee's Minute *29th October 1867*

Character assigned *13A.1* *WMS*

Certificate (if required)