

# ANNUAL SURVEYS.

28728  
*[Signature]*

No. 325 Survey held at London Date Oct 22<sup>nd</sup> to 25<sup>th</sup> 1867  
 on the Ship "Plover" Master J. Gillead  
 Tonnage 414 Built at Sunderland When built 1858  
 By whom built \_\_\_\_\_ Owners Colonial Coy  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock & London Dock

Last Survey, No. 27611 Port of London Classed 13 A. 1.  
66

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good</u>	Pumps } <u>good</u>
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings } <u>firm</u>	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>firm</u>	Do Do at other places <u>where</u>	Sails } <u>where</u>
Planksheers } <u>good</u>	Keelsons	Anchors No. of <u>3 B 1 S 2 K</u>
Sheerstrakes } <u>where</u>	Clamps and Shelves	Cables
Topsides } <u>seen</u>	Ceiling	Hawsers and Warps } <u>seen</u>
Wales } <u>seen</u>	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter <u>sighted</u>	Copper _____ When put on <u>1865</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen  
*now done, the bottom sighted and the Copper patched -*  
*she is now in good condition fit in our opinion*  
*to remain as classed 13 A. 1.*

Committee's Minute 29<sup>th</sup> October 1867 *[Signature]*  
 Character assigned 13 A. 1. M.S.  
Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_