

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 47 Survey held at London Date 12th Nov^r 21st 1867
 on the Ship Falcon Master John Mowlem
 Tonnage 512 Built at Port Glasgow When built 1837
 By whom built _____ Owners Foster & Co.
 Port belonging to London Destined Voyage Murachee
 If Surveyed Afloat or in Dry Dock "King & Queen" & East India docks.

Last Survey, No. 27915 Port London Classed Rest^d/64. Y. A. 1
 REPAIRS 66

Sighted the yellow metal sheathing, and repaired it.
 Caulked from the metal line to gunwale.
 lifted the timbers and overhauled her inside and outside
 as far as practicable, after the removal of a good portion
 of the ballast. —

Present Condition of the

Decks <u>in good order</u>	Treenails <u>where seen</u> <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>firm</u> <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>Certified & clean?</u> <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained <u>from the deck</u> <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3</u> <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Wales <u>"</u>	Rudder <u>efficient</u> <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>F&Y. M.</u> When put on <u>1866</u>	Standing & Running Rigging <u>"</u>
General Observations and Opinion, <u>Caulking of Bottom, Deck, & Waterways. good</u>		

I am of opinion she is entitled to remain as Class'd
Rest^d 64, Y. A. 1.
Samuel Presing

The Amount of Fee.....£ — : — : is received by me,
 Special..... 1 : 1 :
 Certificate (if required) : :

Committee's Minute 29th November 1867
 Character assigned Rest 7 A 1



© 2021

Lloyd's Register
 Foundation

LON652-0451