

28955

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 587 Survey held at London Date Feb 8th 18 68
on the S. " Anglesey Master Mutter
Tonnage 1018 Built at London When built 1852
By whom built Green Owners R. Green
Port belonging to London Destined Voyage Port Philip
If Surveyed Afloat or in Dry Dock in Green's lower and East India Decks

Last Survey, No. 28217 Port London Classed 13 A1
REPAIRS cont. 65. 4. 4. 67

Lifted bowsprit, took down and re-fitted knee of head; renewed upper pieces of apron and stemson of Teak; added an etching piece of English Oak and caulked from metal line to Planksheer.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " "</u>	Breasthooks and Stemson <u>" " "</u>	Pumps <u>" " "</u>
Comings <u>" " "</u>	Transoms, Pointers, and Crutches <u>" " "</u>	Boats <u>" " "</u>
Upper Deck Beams & Fastenings <u>" " "</u>	Timbers of the Frame at the openings <u>" " "</u>	Masts, Yards, &c. <u>" " "</u>
Lower Deck Beams & Fastenings <u>" " "</u>	Ditto Ditto at other places <u>" " "</u>	Condition, how ascertained <u>from enquiry as seen from deck</u>
Planksheers <u>" " "</u>	Keelsons <u>" " "</u>	Sails <u>" " "</u>
Sheerstrakes <u>" " "</u>	Clamps and Shelves <u>" " "</u>	Anchors No. of <u>3 B, 1 S, 2 K,</u>
Topsides <u>" " "</u>	Ceiling <u>" " "</u>	Cables <u>" " "</u>
Wales <u>" " "</u>	Rudder <u>" " "</u>	Hawsers and Warps <u>" " "</u>
Plank (Bottom) and Counter <u>" " "</u>	Copper <u>F Y M</u> When put on <u>1866</u>	Standing & Running Rigging <u>" " "</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where seen Good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ 3 : - : is received by me, John Maxwell

Special..... 1 : 1 : 0

Certificate (if required) : 5 :

Committee's Minute 14th February 18 68

Character assigned Port 4 WMS



© 2019

Lloyd's Register
Foundation

LDN653-0032