

# REPORT of SURVEY for REPAIRS.

28961

No. in Reg. Book. **No.** 166 Survey held at London Date Aug<sup>th</sup> 1 to Sep 5 1867  
 on the Ship "Maori" Master D. F. Roberts  
 Tonnage 179<sup>3</sup> Built at Sunderland When built 1855  
 By whom built \_\_\_\_\_ Owners Suart & Co  
 Port belonging to London Destined Voyage Auckland  
 If Surveyed Afloat or in Dry Dock Limetkiln Dry Dock & East India Dock

Last Survey, No. 27656 Port London Classed 13 A. 1.  
 REPAIRS now done, Cont 64-4-

The Yellow Metal stripped, caulked from keel to the fourth seam of deck, and the bottom resheathed with Yellow Metal on Felt.  
 The lower deck caulked

## Present Condition of the

|   |   |                                       |
|---|---|---------------------------------------|
| Decks                                     | Treenails   | Windlass and Capstan                  |
| Waterways <u>caulked</u>                  | Breasthooks and Stenson                             | Pumps                                 |
| Comings                                   | Transoms, Pointers, and Crutches                    | Boats <u>Five</u>                     |
| Upper Deck Beams & Fastenings             | Timbers of the Frame at the openings                | Masts, Yards, &c.                     |
| Lower Deck Beams & Fastenings             | Ditto Ditto at other places                         | Condition, how ascertained            |
| Planksheers <u>caulked</u>                | Keelsons  | Sails <u>by observation from deck</u> |
| Sheerstrakes <u>do</u>                    | Clamps and Shelves                                  | Anchors No. of <u>3 B. 1 S. 2 H.</u>  |
| Topsides <u>do</u>                        | Ceiling   | Cables                                |
| Wales <u>do</u>                           | Rudder  | Hawsers and Warps                     |
| Plank (Bottom) and Counter <u>caulked</u> | Copper <u>F. &amp; Y. M.</u> When put on <u>now</u> | Standing & Running Rigging            |

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now where seen in good condition fit in my opinion to remain as classed A. 1.

The Amount of Fee.....£ — : — : As received by me.


Special..... 1 : 1 :

Certificate (if required).....

Committee's Minute 18<sup>th</sup> February 18 68

Character assigned Cont 4 A 1

second M was



© 2019

Lloyd's Register Foundation  
 LON653-0060