

ANNUAL SURVEYS.

28967

No. 386 on the Ship "Mars" Survey held at London Date Jan 29th to Feb 7 1868
 Tonnage 721 Built at Sunderland Master G. R. Holman
 By whom built Owners J. Allan
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Lincolin Dry Dock & East India Dock

Last Survey, No. 27861 Port of London. Classed 13 A. 1. 86

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways. <i>caulked</i> } <i>good</i>	Breasthooks and Stemson } <i>good</i>	Pumps } <i>good</i>
Comings	Transoms, Pointers, and Crutches	Boats <i>five</i>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <i>where</i>	Ditto ditto at other places } <i>where</i>	Sails } <i>and</i>
Planksheers <i>caulked</i>	Keelsons	Anchors No. of <i>3 B. 1 S. 2 M</i>
Sheerstrakes <i>caulked</i>	Clamps and Shelves	Cables } <i>efficient</i>
Topsides <i>caulked</i> } <i>seen</i>	Ceiling } <i>seen</i>	Hawsers and Warps
Wales <i>caulked</i>	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <i>F & Y M</i> When put on <i>1866</i>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *good where seen*

Now done, caulked from the metal line to the waterway seam and the bottom sighted and metal patched and payed with Tallow. She is now where seen in good and efficient condition fit in my opinion to remain as

Committee's Minute *18th February 1868*
 Character assigned *13 A. 1 was*

Classed 13 A. 1
Stornish
 Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18

Character assigned _____