

ANNUAL SURVEYS.

29048

No. 710 Survey held at London Date Mar 3rd 7th 18 68
on the 139 "Matilda" Master Redland
Tonnage 239 Built at Bristol When built 1850
By whom built Owners Scrutton S. L
Port belonging to Bristol Destined Voyage not fixed
If Surveyed Afloat or in Dry Dock Union Dry Dock & West India Dock

Nov 14. 3. 68
R. L. W.

Last Survey, No. 27151 Port of London. Classed 12 A. 1 Cont 62 8/4
65

The present Condition of the

Decks	good	Treenails	good	Windlass and Capstan	good
Waterways		Breasthooks and Stemson		Pumps	
Comings	where	Transoms, Pointers, and Crutches	where	Boats	and
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	seen	Ditto ditto at other places	seen	Sails	efficient
Planksheers		Keelsons		Anchors No. of 38 5/24	
Sheerstrakes	seen	Clamps and Shelves	seen	Cables	efficient
Copsides		Ceiling		Hawsers and Warps	
Vales	seen	Rudder	seen	Standing & Running Rigging	efficient
Plank (Bottom) and Counter		Copper T. & V. M. When put on 1863			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
Now done the bottom sighted and the Yellow Metal patched
She is in good condition fit in my opinion to remain as classed A. 1.

Committee's Minute 20th March 18 68
Character assigned Cont 8 A 1 W. R. S.

Half Time Survey under Mr Williamson in Decr 65 Certificate (if required) the main piece of windlass is always exposed

No. Survey held at Date 18
on the Master
Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Copsides	Ceiling	Hawsers and Warps
Vales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways

Committee's Minute 18
Character assigned