

#29113

REPORT of SURVEY for REPAIRS.

No. in Book. No. Survey held at London Date 14<sup>th</sup> 15<sup>th</sup> April 18<sup>th</sup> 1868.  
on the Yawl Wellington Master J. Wilson  
Tonnage 70 built at Sandgate When built 1835.  
By whom built Owners Carr & Co.  
Port belonging to London Destined Voyage Gibraltar  
If Surveyed Afloat or in Dry Dock "Fountain" Ways.

st Survey, No. 28345 Port Lon. Classed Rest<sup>d</sup>/66. S. A. 1.  
PAIRS

Caulked the bottom and sheathed it with  
Linck on felt. —

Condition of the

ays	in good order	Treenails	where seen	good	Windlass and Capstan	in good order
	"	Breasthooks and Stemson	"	"	Pumps	"
	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Deck Beams & Fastenings	firm	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	from the deck "
ers	"	Keelsons	"	"	Sails	"
akes	"	Clamps and Shelves	"	"	Anchors No. of 2	"
	"	Ceiling	"	"	Cables	"
	"	Rudder	efficient	"	Hawsers and Warps	"
Bottom) and Counter	"	Copper	Linck on felt	When put on now	Standing & Running Rigging	"
Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		good where tested.		

I am of opinion this Vessel is entitled to remain as  
Classed Rest<sup>d</sup>/66 S. A. 1.  
Samuel Presious

Amount of Fee.....£ : : is received by me,  
Special..... / : :  
Certificate (if required) : :

ee's Minute 18

er assigned



© 2019

Lloyd's Register  
LON653-0158  
Foundation