

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 28733 Survey held at London Date May 11 to June 8 1868
 on the Bn "Rowena" Master J. Fox
 Tonnage 195 built at P. E. Isle When built 1867
 By whom built Loffin Owners Love & Co.
 Port belonging to London Destined Voyage Cape of Good Hope
 If Surveyed Afloat or in Dry Dock Duke Shore Dry Dock

Last Survey, No. 28733 Port London. Classed 7 A 1
10, 67

REPAIRS

now done,

caulked from the keel to the gunwale and the bottom sheathed with yellow metal on felt - a house 13 feet x 12 feet fitted on the deck -

Present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>Good</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>efficient</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>efficient</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>where</u>	Ditto Ditto at other places <u>where</u>	Condition, how ascertained <u>by insp. from deck</u>
Planksheers <u>caulked</u>	Keelsons <u>Good</u>	Sails <u>good</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>do</u>
Topsides <u>do</u>	Ceiling <u>seen</u>	Cables <u>do</u>
Wales <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>Sufficient</u>
Plank (Bottom) and Counter <u>caulked</u>	Copper <u>IXYM</u> When put on <u>now</u>	Standing & Running Rigging <u>Good</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good and efficient condition fit in my opinion to remain as classed

The Amount of Fee.....£ 10 is received by me,

Special..... / : / :

Certificate (if required) : : :

Committee's Minute 16 June 18 68

Character assigned 7 A 1



© 2019

Lloyd's Register Foundation

LOW653-0257