

REPORT of SURVEY for REPAIRS.

29272

No. in Reg. Book. **No.** Survey held at London Date June 15th 1868
 on the S. Agra Master A. Foss
 Tonnage 665 built at Sunderland When built 1851
 By whom built _____ Owners Lidgett &
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Britannia & E. S. Dock

Last Survey, No. 1273 Port Milford Classed 13 A 1
 REPAIRS cont 64 - 9 5.67

Yellow metal repaired also two anchors. 19.1.10
 17.2.14

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>ETAM</u> When put on <u>1866</u>	Standing & Running Rigging

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good where seen

This vessel is eligible in my opinion to remain classed A 1

Jos. W. Wain

The Amount of Fee.....£ : : is received by me,

Special..... 1: 1: 1868

Certificate (if required) _____

Committee's Minute 26th June 1868

Character assigned Cont 9 A 1 W.A.S.

