

REPORT of SURVEY for REPAIRS.

2951

No. in Reg. Book. **No.** 526 Survey held at London Date July 27th 18 68
 on the S. "Chrysolite" Master M^cPherson
 Tonnage 471 built at Aberdeen When built 1857
 By whom built _____ Owners M^cPherson
 Port belonging to Liverpool Destined Voyage Kanagawa
 If Surveyed Afloat or in Dry Dock Horseferry dock + W.I. Dock

Last Survey, No. 27615 Port London Classed 14 A 1

REPAIRS

Cont 65 - 5
7.66

Yellow metal repaired and painted.

Present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>Good & sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>1 1/2 Yds</u> When put on <u>1856</u>		Standing & Running Rigging	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

*This vessel is eligible in my opinion
to remain classed*

The Amount of Fee.....£ : : is received by me,

Special..... : : :

Certificate (if required) : : :

Committee's Minute 31st July 18 68

Character assigned Cont^d 5 A 1 WAG



© 2019

Lloyd's Register
Foundation

LONG53-0337