

REPORT of SURVEY for REPAIRS.

29393

No. in Reg. Book. **No.** 27 Survey held at London. Date 8th to Aug¹³ 1868
 on the Ship "Valuer fastle" Master A. Tucker Burridge.
 Tonnage 1064 built at Sunderland When built 1855-
 By whom built _____ Owners Green & Co.
 Port belonging to London. Destined Voyage India-
 If Surveyed Afloat or in Dry Dock Green's Lower dock and East India dock

Last Survey, No. 28700 Port London. Classed 13. A. 1.
font 67- for 9 yrs.
10. 67-

REPAIRS

Now done:- Sighted the Bottom and patched the Yellow metal sheathing and painted it with Peacock's Patent paint.- fanked the Main-deck and the Butts of Topsides.-

Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>good and efficient</u>
Waterways		Breasthooks and Stenson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats <u>five</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto Ditto at other places	} <u>where</u>	Condition, how ascertained <u>by observation & inquiry</u>	} <u>good</u>
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B 1 S 2 R</u>	
Topsides		Ceiling		Cables	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Hawsers and Warps	} <u>sufficient</u>
Plank (Bottom) and Counter		Copper <u>164. 4</u> When put on <u>1867</u>		Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		<u>Good where seen.</u>	

She is now in good and efficient condition and fit, in our opinion, to remain classed: A. 1.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 18th August 1868

Character assigned font 9 1/2, 1 was

J. A. Williamson
St. John's



© 2019

Lloyd's Register
 Foundation
 L00653-0366