

# ANNUAL SURVEYS.

29/20

No.

Survey held at

London

Date

August 27<sup>th</sup> 1868

on the

S. Maria

Master

Roberts

Tonnage

703

Built at

Sunderland

When built

1857

By whom built

199

Owners

Smart & Co

Port belonging to

London

Destined Voyage

New Zealand

If Surveyed Afloat or in Dry Dock

in Limekiln Dock

Last Survey, No. 28961

Port of

C.F. London

Classed

13A1

cont 64.4.

The present Condition of the

Decks

where seen Good

Treenails

where seen Good

Windlass and Capstan

Good 9.64

Waterways

Breasthooks and Stemson

Pumps

Comings

Transoms, Pointers, and Crutches

Boats

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Masts, Yards, &c.

Lower Deck Beams & Fastenings

Ditto ditto at other places

Sails

Planksheers

Keelsons

Anchors No. of

3B, 1S, 2K

Sheerstrakes

Clamps and Shelves

Cables

Topsides

Ceiling

Hawsers and Warps

Wales

Rudder

Standing & Running Rigging

Plank (Bottom) and Counter

Copper F.Y.M. When put on

1864

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

where seen Good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute

1<sup>st</sup> September 1868

Character assigned

Cont 4A, 1 was

John Maxwell

Certificate (if required)

No.

Survey held at

London

Date

August 29<sup>th</sup> 1868

on the

S. Hero

Master

Price

Tonnage

676

Built at

Sunderland

When built

1855

By whom built

666

Owners

Spence & Co

Port belonging to

London

Destined Voyage

East India Dock

If Surveyed Afloat or in Dry Dock

in Limekiln Dock

Last Survey, No. 28101

Port of

Ladbroke

Classed

10A1

cont 65.4

The present Condition of the

Decks

where seen Good

Treenails

where seen Good

Windlass and Capstan

Good 2.64

Waterways

Breasthooks and Stemson

Pumps

Comings

Transoms, Pointers, and Crutches

Boats

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Masts, Yards, &c.

Lower Deck Beams & Fastenings

Ditto ditto at other places

Sails

Planksheers

Keelsons

Anchors No. of

3B, 1S, 2K

Sheerstrakes

Clamps and Shelves

Cables

Topsides

Ceiling

Hawsers and Warps

Wales

Rudder

Standing & Running Rigging

Plank (Bottom) and Counter

Copper F.Y.M. When put on

1864

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

where seen Good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute

1<sup>st</sup> September 1868

Character assigned

Cont 7A, 1 was

John Maxwell

Certificate (if required)

Clavi  
Hero



© 2019

Lloyd's Register  
Foundation