

# REPORT of SURVEY for REPAIRS.

29634

No. in Reg. Book. **No.** 93 Survey held at London Date Nov 11<sup>th</sup> 18 68  
 on the B.E. "Adela" Master J. Packman  
 Tonnage 227 built at Grangemouth When built 1865. (5 mo.)  
 By whom built Adamson Owners Brandram B<sup>rs</sup>  
 Port belonging to London Destined Voyage W Indies  
 If Surveyed Afloat or in Dry Dock Up the globe dry dock.

Last Survey, No. 3232 Port Leith Classed G.C. 1. (6.65)  
 REPAIRS Now done.

*Sighted bottom the Yellow Metal Shipped, Caulked from keel to the Plank sheers, and bottom resheathed with Yellow Metal on Felt.*

## Present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>Good and sufficient where seen</i>
Waterways		Breasthooks and Stemson		Pumps <u>2</u>	
Comings		Transoms, Pointers, and Crutches		Boats <u>2</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c. <u>Good</u>	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>inspected and weighing</u>	
Plank sheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. 1 S. 1</u>	
Topsides		Ceiling		Cables	
Wales	Rudder <u>Had good</u>	Hawsers and Warps			
Plank (Bottom) and Counter	Copper <u>and Y.M.</u> When put on <u>now</u>	Standing & Running Rigging			
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways <u>Good where tested.</u>				

*She is now in good and efficient condition and fit in my opinion to remain as Classed Vice*

The Amount of Fee.....£..... is received by me,

Special...../ / 0

Certificate (if required).....

Committee's Minute 24<sup>th</sup> November 18 68

Character assigned 951 record



© 2019

Lloyd's Register Foundation

LON653-0541