

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Supp 24 on the RK. Hopewell Survey held at London Date Dec 7th 18 68
 Tonnage 602 built at Bideford When built 1868
 By whom built fox Owners J. Shepherd
 Port belonging to London Destined Voyage Kanagawa
 If Surveyed Afloat or in Dry Dock in Union & West India Docks

Last Survey, No. 1563 Port Bideford Classed 13 A1
 68

REPAIRS

Sheathed with Yellow metal over felt, and renewed one length of waterway on Starboard side of Leak.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from engine has seen from deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3B, 1S. 2K</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>YM</u> on <u>felt</u> When put on <u>1868</u>	Standing & Running Rigging

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. when tested good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ : : is received by me, Thos Maxwell

Special..... / : / : 0 0 0

Certificate (if required) : :

Committee's Minute 29th December 18 68

Character assigned 13A 1

record YM was



© 2019

Lloyd's Register Foundation

LN654-0025