

29915

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 863 Survey held at London Date 11<sup>th</sup> February 18 69  
on the Wood ship Stonehouse Master C. Bley.  
Tonnage 1153 Built at Pallion When built 1866  
By whom built Summerville Owners J. Monison  
Port belonging to London Destined Voyage London to India  
If Surveyed Afloat or in Dry Dock Victoria Porttoons

Last Survey, No. 28790 Port London Classed 13. AI  
REPAIRS Now done

Vessel in dry dock. Yellow Metal Sheathing shipped and caulked from Keel to Gunwale. Re-sheathed with Yellow Metal on Deck. — A new Iron Main Mast Supplied  $29\frac{1}{2}$  in three plates of  $\frac{1}{2}$  with three angle Irons, Butts shroul and lands single rivetted.

## Present Condition of the

Decks	<u>good</u>	Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	<u>good</u>
Comings	<u>good and new</u>	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	<u>good</u>
Lower Deck Beams & Fastenings	<u>good</u>	Ditto Ditto at other places		Condition, how ascertained	<u>from the deck</u>
Planksheers		Keelsons		Sails	<u>sufficient</u>
Sheerstrakes		Clamps and Shelves		Anchors No. of	<u>3 B. 1 S. 2 K.</u>
Topsides		Ceiling		Cables	<u>sufficient</u>
Wales		Rudder		Hawsers and Warps	<u>good &amp; sufficient</u>
Plank (Bottom) and Counter		Copper <u>Yellow Metal</u> When put on <u>1869</u>		Standing & Running Rigging	<u>good</u>
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	<u>new and good</u>		

Is now in good order and condition, and eligible in my opinion to remain as Classed 13. AI

The Amount of Fee.....£ - : - is received by me,

Special..... 2 : 2 : 0

Certificate (if required) : : 3 : 0

Committee's Minute 23<sup>rd</sup> February 18 69

Character assigned 13. AI

record



© 2019

Lloyd's Register  
Foundation

LONGST 0109