

#29985

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.**                      Survey held at London Date May 9<sup>th</sup> 18 68  
on the S<sup>re</sup> Pride of the Ocean Master Duke  
Tonnage 1169 built at United States When built                       
By whom built                      Owners J. Gunn  
Port belonging to London Destined Voyage                       
If Surveyed Afloat or in Dry Dock in Green's lower & Victoria Docks

Last Survey, No. 1312 Port Milford Classed                     

## REPAIRS

The Owner of this vessel being desirous of placing her on the A character requested <sup>that</sup> a survey be held upon her for that purpose, upon attending at the ship and making a careful (preliminary) examination we found several timbers in the fore body in the lower hold more particularly upon the starboard side as well as the thick bilge strakes on each side in a very unsatisfactory state; recommended that the ship should be further opened for the removal of the defective timbers also that the objectionable bilge strakes be renewed, upon these recommendations being made the Owner declined to proceed further with the survey and the vessel has been taken out of dry dock.

### Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

The Amount of Fee.....£ : : is received by me,  
Special..... 2 : 2 : 0  
Certificate (if required) : :

Committee's Minute 18  
Character assigned

*John Maxwell*  
*Thos. W. Vauw*

