

REPORT of SURVEY for REPAIRS.

No. 186 on the Result Survey held at London Date Feb 27th 1869
 Master J. Pittman
 Tonnage 160 Built at Jersey When built 1863
 By whom built _____ Owners Edw^d Pickolls
 Port belonging to Whitstable Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Fore and aft dock

Last Survey, No. 1135 Port Jersey Classed 10 A 1

REPAIRS

Listings cut out in accordance with the Rule and the
 frame found all good, Ironails and bolts driven out
 scraped bright where required, Windlass stripped and
 found good, chains ranged and all requirements
 complied with.

Three planks on port buttock renewed

G.M. stripped & renewed.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>IM</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in good and efficient
 condition and having complied with the require-
 ments is eligible in my opinion to remain

The Amount of Fee.....£ : : is received by me, Classed A 1
 Special..... 2 : 2 : Pair and marked (HT. 69)
 Certificate (if required) : 2 : 6

Committee's Minute 30th March 1869

Character assigned 10 A 1 HT. 69

Jos. W. Wain



Lloyd's Register
Foundation
LON654-0185