

REPORT of SURVEY for REPAIRS:

No. in Reg. Book. **No.** Survey held at London Date 19th March 18 69
 on the 1/3rd West Master
 Tonnage 386 built at Sunderland When built 1848
 By whom built 409 Owners Wright & Co
 Port belonging to London Destined Voyage Falkland Island
 If Surveyed Afloat or in Dry Dock Globe dock + W I Dock

Last Survey, No. 20909 Port Liverpool Classed 13 A 1
 REPAIRS Cont 51-9-10.67-

Gellow metal repaired -

Surveyed 1/2 time on Survey London 27/6/68 August/66

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>Good and</u>
Planksheers <u>Good</u>	Keelsons	Sails <u>sufficient</u>
Sheerstrakes <u>where seen</u>	Clamps and Shelves <u>where seen</u>	Anchors No. of <u> </u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>F. J. M.</u> When put on <u>1866</u>	Standing & Running Riggings
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where seen</u>	

This vessel is now in good condition and is eligible in my opinion to remain as classed

Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required) : 5 : -

Committee's Minute 2nd April 18 69

Character assigned Cont 9 A 1

Thos. Br Wawn



© 2019

Lloyd's Register Foundation

LON654-0194