

30061

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 449 Survey held at London Date 22nd April 1869
 on the Ship "Shun Lee" Master John Milbanke
 Tonnage 674 built at London When built 1866-7 mo
 By whom built Walker Owners M. Walker
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock Carender's dry dock and Afloat.

st Survey, No. 28860 Port London. Classed 14 A1.
 IRS 12-67

stripped Yellow Metal Sheathing, some few of the
 thro' fastenings of inner skin driven out for survey and
 no one in good condition. Caulked from keel to metal line
 & resheathed bottom with Yellow Metal on felt.

ent Condition of the

erways

ngs

er Deck Beams & Fastenings

er Deck Beams & Fastenings

ksheers

rstrakes

Topsides

Wales

Plank (Bottom) and Counter

eneral Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper As perWhen put on corr

Caulking of Bottom, Deck, & Waterways.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained seen from the deck

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Amount of Fee.....£ : : is received by me,

Special..... / : / :

Certificate (if required) : 5 :

Committee's Minute 24th April 1869Character assigned 14 A1

© 2019

Lloyd's Register

Foundation 0236