

ANNUAL SURVEYS.

30073

No. 183 Survey held at London Date 27th April 1869
 on the bark "Vinegar" Master L. H. Williamson
 Tonnage 561 Built at Sunderland When built 1844
 By whom built W. Kaynes Owners W. Kaynes
 Port belonging to Liverpool Destined Voyage St. Janeiro
 If Surveyed Afloat or in Dry Dock Afloat in the London Docks

Last Survey, No. 3671 Port of Hull Classed A 1 in Red
S. S. 186-7 yrs. 6-66

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>1/4 in</u> When put on <u>1866</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where Examined
Hedge Anchor including stock 2-2-0 now supplied.
Is now in good and efficient condition fit for the safe con-
voyance of dry and perishable cargoes to and from all parts of the
 Committee's Minute 30th April 1869 Work and in my opinion eligible to remain
 Character assigned As classed A 1 in Red W. H. Moore.
 Certificate (if required).

No. 298 Survey held at London Date 27th April 1869
 on the bark "Torres" Master W. H. Moore
 Tonnage 243 Built at Neulmein When built 1857
 By whom built W. H. Moore Owners W. H. Moore
 Port belonging to London Destined Voyage Alger Bay
 If Surveyed Afloat or in Dry Dock New frame dry dock.

Last Survey, No. 29262 Port of London Classed B 41.
Port 64-9 yrs. 6-68

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>1/4 in</u> When put on <u>1868</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where Examined
Patched Cedar Metal sheathing Rails and bulwarks part new
Is now in good and efficient condition and in my
 Committee's Minute 30th April 1869 opinion eligible to remain as classed.
 Character assigned Port 9 in 1 WAS W. H. Moore.
 Certificate (if required).

LON 654-0247