

REPORT of SURVEY for REPAIRS.

30173

No. in Reg. Book. **No.** 420 Survey held at London Date March 18 69
 on the S^a Pince Master W Steel
 Tonnage 76 built at Jersey When built 1840
 By whom built _____ Owners W Steel
 Port belonging to Jersey Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fountain dock

Last Survey, No. 1452 Port Surr. Classed S. N. 1

REPAIRS

Length 78 2/10 feet

One length of after tree and garboard of Elm and Pitch Pine, deadwood of second hand English Oak Rudder trunk renewed also two pintles and braces, ceiling repaired also the vessel recaulked over all.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>Good</u>
Planksheers	Keelsons	Sails
Sheerstrakes <u>where seen</u>	Clamps and Shelves <u>where seen</u>	Anchors No. of <u>sufficient</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen tested

This vessel is eligible in my opinion to remain as classed N. 1

The Amount of Fee.....£ - : 10 : - is received by me,

Special..... - : 10 : 6

Certificate (if required) - : -

Committee's Minute 18th June 18 69

Character assigned N. 1

record repair

Mr J Carr Morgan and Lane



© 2019

Lloyd's Register Foundation

LON654-0325

Price

