

# ANNUAL SURVEYS.

30299

No. 404 Survey held at London Date 11<sup>th</sup> August 1869  
 on the Ship "Fugitive" Master N. R. Barwood  
 Tonnage 471 Built at Sunderland When built 1864 6 Mo  
 By whom built Gardner Owners J. B. Walker  
 Port belonging to London Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock West India Docks

Last Survey, No. 29470 Port of Lon.

Classed 10 A1  
 H.T. 68 9.68

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Y and Y.M.</u> When put on <u>1868</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Mixer Mast renewed of Pine.  
Is now in good and efficient condition, and in our opinion eligible to remain as classed.

Committee's Minute 20<sup>th</sup> August 1869

Character assigned 10 A1 was

Jm Moverly  
W. B. Fisher

Certificate (if required).

No. 265 Survey held at London Date 10<sup>th</sup> to 12<sup>th</sup> Aug<sup>r</sup> 1869

on the Ship "Helenstee" Master

Tonnage 798 Built at Dumbarton When built 1862 1 Mo

By whom built M<sup>c</sup> Millen Owners Albion S. Comp<sup>y</sup>

Port belonging to Glasgow Destined Voyage New Zealand

If Surveyed Afloat or in Dry Dock Canal Dry dock, and Afloat.

Last Survey, No. 28110 Port of Glasgow

Classed 10 A1  
 H.T. 68 5.68.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Y and Y.M.</u> When put on <u>1868</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Patched yellow metal sheathing, and repaired Bulwarks.  
Is now in good and efficient condition, and in our opinion eligible to remain as classed.

Committee's Minute 20<sup>th</sup> August 1869

Character assigned 10 A1 was

Certificate (if required).

LON654 - 0429