

# REPORT of SURVEY for REPAIRS.

30393

No. in Reg. Book. **No.** 170 Survey held at London Date 15<sup>th</sup> Sep<sup>r</sup> 20<sup>th</sup> 1869  
 on the Barque Westmoreland Master J. Gasking  
 Tonnage 452 built at Sunderland When built 1858  
 By whom built — Owners Anderson  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock "Bull head" dry dock and afloat

Last Survey, No. 27782 Port Lon. Classed 13. A. 1.  
 9.66

## REPAIRS

Stripped off the Yellow Metal  
 Caulked up to metal line, and re-sheathed  
 with Yellow Metal on felts. —

### Present Condition of the

|                                   |      |  |                                    |      |                            |                   |
|-----------------------------------|------|--|------------------------------------|------|----------------------------|-------------------|
| Decks                             | good | Treenails                              | where seen                         | good | Windlass and Capstan       | in good order     |
| Waterways                         | "    | Breasthooks and Stemson                | "                                  | "    | Pumps                      | "                 |
| Comings                           | "    | Transoms, Pointers, and Crutches       | "                                  | "    | Boats                      | "                 |
| Upper Deck Beams & Fastenings     | firm | Timbers of the Frame at the openings   | "                                  | "    | Masts, Yards, &c.          | "                 |
| Lower Deck Beams & Fastenings     | "    | Ditto Ditto at other places            | "                                  | "    | Condition, how ascertained | from the Deck     |
| Planksheers                       | "    | Keelsons                               | "                                  | "    | Sails                      | "                 |
| Sheerstrakes                      | "    | Clamps and Shelves                     | "                                  | "    | Anchors No. of             | 3.                |
| Topsides                          | "    | Ceiling                                | "                                  | "    | Cables                     | "                 |
| Wales                             | "    | Rudder                                 | efficient                          | "    | Hawsers and Warps          | "                 |
| Plank (Bottom) and Counter        | "    | Copper                                 | Let by m <sup>rs</sup> When put on | now  | Standing & Running Rigging | "                 |
| General Observations and Opinion, |      | Caulking of Bottom, Deck, & Waterways. |                                    |      |                            | good where tested |

As far as seen, she appears to be in good condition  
 and is in my opinion entitled  
 to remain at Class 13. A. 1.

The Amount of Fee.....£ — : — : is received by me,  
 Special..... / : / :  
 Certificate (if required)..... : : :

Committee's Minute 1<sup>st</sup> October 1869

Character assigned 13A1

© 2021

Lloyd's Register  
 Foundation

LON 655-0013



© 2021

Lloyd's Register  
Foundation