

REPORT of SURVEY for REPAIRS.

0. in
Book. **No.** Survey held at London Date 28th Feb^r Oct^r 1869
03 on the Parque Cliv Master J. W. Honeyborne
Tonnage 371 built at Sunderland When built 1845.
By whom built Owners A. B. Simpson
Port belonging to London Destined Voyage Bombay
If Surveyed Afloat or in Dry Dock

East Survey, No.

29334 Port Lon.

Classed

$$\begin{array}{r} 12 \\ C \\ 4 \\ S.S. \cancel{102}, \quad S.A. 1 \text{ in red} \\ \hline 66 \end{array}$$

REPAIRS

Stripped off the whole of the Yellow Metal Sheathing
Overhauled and made good the Caulking up to metal line.
Fitted New Knees to the Garrick Posts.

Reinforced with yellow metal on felt up to
about 13 feet. —

Proved at recognized
Machines { Examined the Chain Cables, viz 90 fms of 1 5/16 proved up to 31 1/2 2
and ———— " ———— " 30 ———— 1 3/4 original chain. " ————
not proved at { " ———— " ———— 120 ———— 1 1/4 1 5/16 = 28 fms 2 Ch
a recognized Machine { " ———— " ———— 31 ———— 0 0 0
Chain recognized Machine { Bower Anchor of 15 Ch. D. 10 = 16 " 12 proved by A. J. J. " 1 3/16 ———— 31 " 0 " 0
" ———— " ———— 15 Ch - 1 " 2 = 16 " 15 Ch. - not recognized

See the Owners Letter with reference to the Chain Cables and Anchor,

Present Condition of the

Decks	<i>good</i>	Treenails	<i>where seen</i>	<i>good</i>	Windlass and Capstan	<i>in good order</i>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	<i>firm</i> "	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	<i>from the Deck</i> "
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors	No. of <i>3</i> "
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	"	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<i>See & sym. H</i> When put on	<i>now</i>	Standing & Running Rigging	"
Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		<i>good where tested.</i>		

Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good where tested.

She appears to be in good condition and I am of opinion

She is eligible to remain as Chapin

The Amount of Fee.....£ - : - : is received by me,

Special..... 2 : 2 :

Certificate (if required) : 3/ :

Committee's Minute 10th October 18 49

Character assigned

$\triangle^2 = \text{in Red}$

in led
record Y.M. M.D.

© 2021

Lloyd's Register
Foundation

20A 655-0054