

ANNUAL SURVEYS.

30472
Rev 30/10/69

No. 1041 Survey held at London Date 19th October to 29th Oct 18 69
on the Ship "Monarchy" Master A. Day
Tonnage 701 Built at Liverpool When built 1851
By whom built Challoner Owners Browne &
Port belonging to Liverpool Destined Voyage Bombay
If Surveyed Afloat or in Dry Dock Limekiln Dry Dock and East India Docks

Last Survey, No. 29188 Port of Lon. Classed Cont 64 9A.1
(5-68)

The present Condition of the

Decks	Good where seen	Treenails	Good where seen	Windlass and Capstan	Good and sufficient
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper ^{Felt and} Yellow Metal When put on 1868			
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways		Good	

The bottom sighted, and yellow metal patched.

Is in good condition, and in my opinion eligible to remain as classed (viz)

Cont 64 - 9A.1

Committee's Minute 2nd November 1869

Character assigned Cont 9 A 1 MAS

Jon J. Bone.

Certificate (if required).

No. 145 Survey held at London Date 25th to 29th October 18 69
on the Barque "Regia" Master Davidson
Tonnage 418 Built at Bristol When built 1862 - 3ms.
By whom built Hill Owners C. Dawson
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock Limehouse Dry Dock and East India Dock

Last Survey, No. 29139 Port of Lon. Classed 10.A.1.
(4.68)

The present Condition of the

Decks	Good where seen	Treenails	Good where seen	Windlass and Capstan	Good and sufficient
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper ^{Paper &} Yellow Metal When put on 1868			
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways		Good	

The bottom sighted, yellow metal patched, and bulwark-bathing repaired.

Is in good condition and fit in my opinion to remain as classed.

(viz) 10.A.1.

Committee's Minute 2nd November 1869

Character assigned 10 A 1 MAS

Jon J. Bone

Certificate (if required).

LON 655-0071