

ANNUAL SURVEYS.

30501

Recd 12/11/69

No. _____ Survey held at London Date 27th October to 10th November 1869
 on the Barge "Amicus" Master Dolbel
 Tonnage 511 Built at Jersey When built 1856
 By whom built Le Bescont Owners Orange & Co
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Linehouse Dry Dock and East India Docks

Last Survey, No. 1366 Port of Jersey Classed Cont^d 67, S.A. 1
 Present Condition of the 20 Left Cut

Waterways	Treenails	Windlass and Capstan
Decks	Breasthooks and Stemson	Pumps
Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Boats
Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Sheers	Ditto ditto at other places	Sails
Strakes	Keelsons	Anchors No. of
Planks	Clamps and Shelves	Cables
(Bottom) and Counter	Ceiling	Hawsers and Warps
	Rudder	Standing & Running Rigging
	Copper <u>Left and Yellow Metal</u> When put on <u>1868</u>	
	Caulking of Bottom, Deck, and Waterways <u>Good</u>	

Observations and Opinion, Bottom sighted and yellow metal patched in good condition and in my opinion fit to remain as classed Cont^d 8.A.1.

Surveyor's Minute 15th November 1869
 Certificate assigned Cont^d S.A. 1
J. J. Bone

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18__
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 Surveyed Afloat or in Dry Dock _____

Present Condition of the _____ Classed _____

Waterways	Treenails	Windlass and Capstan
Decks	Breasthooks and Stemson	Pumps
Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Boats
Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Sheers	Ditto ditto at other places	Sails
Strakes	Keelsons	Anchors No. of
Planks	Clamps and Shelves	Cables
(Bottom) and Counter	Ceiling	Hawsers and Warps
	Rudder	Standing & Running Rigging
	Copper _____ When put on _____	
	Caulking of Bottom, Deck, and Waterways _____	

Observations and Opinion, _____

Surveyor's Minute _____ 18__
 Certificate assigned _____

