

*Composite*  
**ANNUAL SURVEYS.**

30581

No. 1025 Survey held at London Date 7<sup>th</sup> to 17<sup>th</sup> December 1869  
 on the Ship "Mofussilite" Master A. C. Rae.  
 Tonnage 1009 Built at Glasgow When built 1864. 9 mo.  
 By whom built Stephen Owners Allan & Sons.  
 Port belonging to London Destined Voyage Madras.  
 If Surveyed Afloat or in Dry Dock Lineholm Dry Dock and East India Dock.

Recd 10/12/69

Last Survey, No. 29986 Port of London Classed 17.A.1  
 (3-69)

The present Condition of the

Decks	Treenails <u>new bolts</u>	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	<u>stungas</u> Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>2 1/2</u> When put on <u>1869</u>	

*Good where seen* (written vertically in the left margin)  
*Good where seen* (written vertically in the middle margin)  
*Good and sufficient* (written vertically in the right margin)

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where exam<sup>d</sup>  
Bottom sighted, and yellow metal patched.  
Is in good condition, and in my opinion, fit to remain as classed, (viz) 17.A.1.

Committee's Minute 21<sup>st</sup> December 1869  
 Character assigned 17.A.1  
 Certificate (if required)

*Wm J. Bone.*

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_