

30634

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 205 No. 1126 Survey held at London Date, first Survey 6th Dec^r Last Survey 8th Jan^r 1869-70
on the Composite Ship "Wild Deer" Master A. Mc. Savish
Tonnage 1126 built at Glasgow When built 1863 12 Mo
By whom built Cornell Owners Albion Shipping Co.
Port belonging to Glasgow Destined Voyage Shanghai
If Surveyed Afloat or in Dry Dock Canal Dry Dock.

Last Survey, No. 29718 Port Lon. Classed 14 A1.
12, 68. (B.S.)

REPAIRS, &c. Yellow metal stripped. Bottom caulked from keel to metal-line, and retalled on felt.

Present Condition of the

Decks	} <u>Good</u> <u>where</u> <u>seen.</u>	Treenails <u>Fastenings C.F.</u>	} <u>Good</u> <u>where</u> <u>seen.</u> <u>Now.</u>	Windlass and Capstan	} <u>Good and efficient.</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>From the deck.</u>	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shells		Anchors No. of <u>Good and</u>	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps <u>sufficient.</u>	
Plank (Bottom) and Counter		Copper <u>Y. Metal</u> When put on <u>Now.</u>		Standing & Running Rigging	
Engine Room Skylights	Caulking of				
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>Good where tested.</u>	Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u> Hatches <u>Good.</u>			

General Observations and Opinion, Is in good and efficient condition and fit in my opinion to remain as classed - 14 A1.
J. H. Eastlake.

The Amount of Entry Fee.....£ - : : is received by me,
Special..... 1 : 1 : 0
Certificate (if required) : : :

Committee's Minute 18th January 1870
Character assigned 14 A1 record