

ANNUAL SURVEYS.

30647
No. 26. 1. 71

No. 74 Survey held at London Date 9th December 1869
on the Wooden Ship "Star of China" Master Angus
Tonnage 794 Built at Aberdeen When built 1862
By whom built Hall Owners H. Adamson
Port belonging to Aberdeen Destined Voyage Port Phillip
If Surveyed Afloat or in Dry Dock Wigram's Dry Dock.

Last Survey, No. 29698 Port of London. Classed 14 A1.
H.T. 68.
12, 68.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>4. 11. on 4.</u> When put on <u>1868.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Yellow metal patched.
Is now in good and efficient condition and fit in my opinion to
remain as classed - 14 A1. Thos. McHaw

Committee's Minute 28th January 1870

Character assigned 14 A1

Certificate (if required)

No. 346 Survey held at London Date 22nd Dec^r - 18th Jan^y 1869-70
on the Wooden Ship "Ceres" Master W. Cochrane
Tonnage 861 Built at Quebec When built 1860
By whom built Gingra Owners J. Cochrane
Port belonging to Greenock Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock Green's Lower Dry Dock.

Last Survey, No. 5470 Port of Greenock. Classed 7 A1.
Cont. June 68-5.
10, 68.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>4. 11. on 4.</u> When put on <u>1868.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Yellow metal patched and coated with Peacock's composition. New
main-mast of Oregon.
Is now in good and efficient condition and fit in my opinion to
remain as classed - Continued June 68-54 years. J. H. Eastlake.

Committee's Minute 28th January 1870

Character assigned Cont 5 1/2 1

Certificate (if required)