

REPORT of SURVEY for REPAIRS.

30654

No. in Reg. Book. **No.** _____ Survey held at London Date January 22nd 1870
 Supp on the Brig "Adolphe & Laura" Master S. L. Couteur
 44 Tonnage 174 Built at Nantes When built 1867
 By whom built _____ Owners Messrs Beckmann & Barnett
 Port belonging to London Destined Voyage Pio Grande
 If Surveyed Afloat or in Dry Dock S^t Katherine's Dock -

Last Survey, No. 1319 Port Palmouth. Classed 12 A
 12. 69

REPAIRS Please see the Palmouth Report No 1319 -
Now done; the Anchors and Chain Cables tested at the
Society's Proving House Poplar, and the Test Certificates
Signed L. R. Isitt - Produced, -
183 Fathom of 1 1/2 Chain Cable tested to 20 3/10 Tons

No	Anchor	wt	gr	lb	Tested to	Ton	cwt
1-	9"	1	26	- 4 1/2	swell	11	1
1-	9"	3	15	"	"	11	10
1-	2"	3	2	"	"	5	5

Chain Cables ranged on deck for examination.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>2 B. 1 S. 1 H</u>
Topsides	Ceiling	Cables <u>183 Fath 1 1/2</u>
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging

General Observations and Opinion.

Caulking of Bottom, Deck, & Waterways.

This vessel was laden when the Survey was requested
for the examination of the Chain Cables &c -
The requirements of the Rules having now been
Complied with - I respectfully recommend the class
to be 12 A 1 -


The Amount of Fee.....£..... is received by me.

Special.....

Certificate (if required) : 2 : 9

Committee's Minute 28th January 1870

Character assigned 12 A 1



© 2021

Lloyd's Register
Foundation