

ANNUAL SURVEYS.

30709

No. 162 Survey held at London Date 17<sup>th</sup> Feby 23<sup>rd</sup> 1870  
on the Ship Carnaguheen Master Wm Colville  
Tonnage 825 Built at Aberdeen When built 1864  
By whom built Humphry Owners Connors &  
Port belonging to Aberdeen Destined Voyage Adelaide  
If Surveyed Afloat or in Dry Dock King & Queen dry dock

Rev 26/12/40

Last Survey, No. 30012 Port of London. Classed G.A. 1, c.f. 69

The present Condition of the

Decks	good	Treenails	where seen	good	Windlass and Capstan	in good order
Waterways	//	Breasthooks and Stemson		//	Pumps	//
Comings	//	Transoms, Pointers, and Crutches		//	Boats	//
Upper Deck Beams & Fastenings	//	Timbers of the Frame at the Openings		//	Masts, Yards, &c.	//
Lower Deck Beams & Fastenings	//	Ditto ditto at other places		//	Sails	//
Planksheers	//	Keelsons		//	Anchors No. of 3 &	//
Sheerstrakes	//	Clamps and Shelves		//	Cables	//
Topsides	//	Ceiling		//	Hawsers and Warps	//
Wales	//	Rudder	efficient	//	Standing & Running Rigging	//
Plank (Bottom) and Counter	//	Copper	Felt & Ymst When put on 1869			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Fitted a New front to the Pop deck and sighted the bottom.  
Sam of opinion she is enabled to remain  
as classed G.A. 1.  
Samuel Presing

Committee's Minute 1<sup>st</sup> March 1870

Character assigned G.A. 1, c.f. 69

Certificate (if required)

D  
W  
C  
U  
No. Survey held at Date 18  
on the Master  
Tonnage Built at When built  
By whom built Owners  
Port belonging to Destined Voyage  
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute 1<sup>st</sup> March 1870

Character assigned

LON 655-0237



Cannaga River low



© 2021

Lloyd's Register  
Foundation