

REPORT of SURVEY for REPAIRS.

30759

No. in Reg. Book. 209 No. 209 Survey held at London Date, first Survey 15th March Last Survey March 18th 1870
 on the Ship Ornate Master J. Sampson
 Tonnage 138 built at Harwich When built 1865
 By whom built Vaux Owners J. Morison
 Port belonging to London Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock Bull head dry dock

Last Survey, No. 28820 Port Lon. Classed 10. A. 1.

REPAIRS, &c.

*Stripped off the whole of the Yellow metal.
 Caulked from Keel to Metal line, and restucced with
 yellow metal on felk.—
 Memo named the "half time survey" to the Owners.*

Present Condition of the

Decks <i>good</i>	Treenails <i>where seen good</i>	Windlass and Capstan <i>in good order</i>
Waterways "	Breasthooks and Stemson "	Pumps "
Comings "	Transoms, Pointers, and Crutches "	Boats "
Upper Deck Beams & Fastenings "	Timbers of the Frame at the openings "	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Ditto Ditto at other places "	Condition, how ascertained <i>from the Deck</i> "
Planksheers "	Keelsons "	Sails "
Sheerstrakes "	Clamps and Shelves "	Anchors No. of <u>34</u> "
Topsides "	Ceiling "	Cables "
Wales "	Rudder <i>efficient</i> "	Hawsers and Warps "
Plank (Bottom) and Counter "	Copper <i>well & good</i> When put on <i>new</i> "	Standing & Running Rigging "
Engine Room Skylights	Caulking of <i>good</i>	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <i>where tested</i>	
	Scuppers <i>good</i>	Cargo and Main Hatchways <i>good</i> Hatches <i>good</i>

General Observations and Opinion,

*As far as seen She appears to be in good condition
 and in my opinion is entitled to remain as
 Class'd 10. A. 1.
 Samuel Presnors*

The Amount of Entry Fee.....£ : - : } is received by me,

Special..... / : / : }

Certificate (if required) : 5 : }

Committee's Minute 1st April 1870

Inspector assigned 10th April

record G.M.



© 2021

Lloyd's Register
 Foundation

LON 655-0270

Ornate

REPORT OF SURVEY FOR REPAIRS.



© 2021

Lloyd's Register
Foundation