

REPORT of SURVEY for REPAIRS.

30806

No. in Reg. Book. **No.** Survey held at London Date, first Survey 4th April Last Survey April 12th 1870
on the Ship Aboukir Master H. Jervais W. Landland
Tonnage 448 built at New Brunswick When built 1861
By whom built Milledge Owners Potter & Co.
Port belonging to Glasgow Destined Voyage Auckland
If Surveyed Afloat or in Dry Dock Limehouse Dry dock
Last Survey, No. 21690 Port Liv. Classed C 1870
1. 69

REPAIRS, &c.

*Stripped off the Yellow Metal Sheathing
Caulked up to metal line and resheathed with Yellow metal on jelly.*

Present Condition of the

Decks	<i>good</i>	Treenails	<i>where seen</i>	<i>good</i>	Windlass and Capstan	<i>in good order</i>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	<i>firm</i>	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	<i>from the deck</i>
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors	No. of <i>3 & 2.1</i>
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	<i>efficient</i>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<i>well 49ms</i>	<i>When put on now</i>	Standing & Running Rigging	"
Engine Room Skylights	"	Caulking of	<i>good where</i>	<i>best</i>	Cargo and Main Hatchways	<i>good</i>
General Observations and Opinion,	"	Bottom, Deck, & Waterways	<i>Wales fitted & sheathed by Port & Starboard since 1862</i>	<i>Scuppers</i>	Hatches	<i>good</i>

Survey'd her in ballast.

*As far as seen she appears to be in good condition and is
in my opinion entitled to remain
as class'd A. 1.*

The Amount of Entry Fee.....£ — : — : } is received by me,
Special..... 2 : 2 : }
Certificate (if required) : 5 : }

Committee's Minute 22nd April 18 70

Character assigned Cont 2 A 1



© 2021

Lloyd's Register
Foundation

LON 655-0308