

REPORT of SURVEY for REPAIRS.

30820
[Signature]
 Recd 20/4/90

No. in Reg. Book. *436* No. *581* Survey held at *London* Date, first Survey *April 16th* Last Survey *April 19th 1870*
 on the *Ship Corea* Master *B. Carr*
 Tonnage *581* built at *Workington* When built *1859*
 By whom built *Fell* Owners *Bushby*
 Port belonging to *Workington* Destined Voyage *✓*
 If Surveyed Afloat or in Dry Dock *Keinekin Dry dock*
 Last Survey, No. *29177* Port *Lon.* Classed *14. A. 1.*
68

REPAIRS, &c.

*Stripped off the Yellow metal sheathing
 Caulked up to metal line, and resheathed with
 Yellow metal on paper* *X See below 'Paper' 2" which*

Present Condition of the

Decks	<i>good</i>	Treenails	<i>when seen</i>	<i>good</i>	Windlass and Capstan	<i>new in 66</i>	<i>in good order</i>
Waterways	"	Breasthooks and Stenson		"	Pumps		"
Comings	"	Transoms, Pointers, and Crutches		"	Boats		"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		"	Masts, Yards, &c.		"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Condition, how ascertained	<i>from the Deck</i>	"
Planksheers	"	Keelsons		"	Sails		"
Sheerstrakes	"	Clamps and Shelves		"	Anchors	No. of <i>34</i>	"
Topsides	"	Ceiling		"	Cables		"
Wales	"	Rudder	<i>efficient</i>	"	Hawsers and Warps		"
Plank (Bottom) and Counter	"	Copper	<i>put on</i>	<i>now</i>	Standing & Running Rigging		"
Engine Room Skylights	"	Caulking of	<i>good</i>	<i>where tested</i>			
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways			Cargo and Main Hatchways	<i>good</i>	<i>good</i>
General Observations and Opinion,		Scuppers	<i>good</i>		Hatches	<i>good</i>	

Surveyed her in ballast.
*She appears to be in good condition, and is in my opinion
 entitled to remain as classed.*
14. A. 1.
Samuel Perkins

The Amount of Entry Fee.....£ - : - : } *is received by me,*
 Special..... *2 : 2* : }
 Certificate (if required) : *5* : }
 Committee's Minute *29 April* 18 *70*
 Character assigned *14 A 1*
[Signature]

Coreas



© 2021

Lloyd's Register
Foundation