

# ANNUAL SURVEYS.

30876

No. 13 Survey held at London Date 16<sup>th</sup> May 24<sup>th</sup> 1870  
 on the Ship La Hague Master W. Goddard  
 Tonnage 1331 Built at Sunderland When built 1865  
 By whom built Owners Revitt & Co  
 Port belonging to London Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Fleetland Dry Dock

Last Survey, No. 30170 Port of Lon. Classed Cons<sup>d</sup>/68. G. A. I. 6.69

The present Condition of the

Decks	good	Treenails	where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	"
Planksheers	"	Keelsons		"	Anchors No. of 3 & 1 S. 2 K	"
Sheerstrakes	"	Clamps and Shelves		"	Cables	"
Topsides	"	Ceiling		"	Hawsers and Warps	"
Wales	"	Rudder	efficient	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper	Fe 4 1/2 mm When put on 1868			
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways good					

She appears to be in good condition, and is in my opinion, entitled to remain as classed Cons<sup>d</sup>/68 - G. A. I. Samuel Presious

Committee's Minute 24<sup>th</sup> May 1870  
 Character assigned Cons<sup>d</sup> 9 1 WWT

Certificate (if required)

No. 99 Survey held at London Date 19<sup>th</sup> May 23<sup>rd</sup> 1870  
 on the Ship Couenakyle Master A. Morrison  
 Tonnage 579 Built at Aberdeen When built 1862  
 By whom built Hall Owners J. Jameson  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Ratcliff Croft Dry Dock

Last Survey, No. 29801 Port of Lon. Classed 13. A. I. H. T. 109 2.69

The present Condition of the

Decks	good	Treenails	where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	"
Planksheers	"	Keelsons		"	Anchors No. of 3 & 1 S. 2 K	"
Sheerstrakes	"	Clamps and Shelves		"	Cables	"
Topsides	"	Ceiling		"	Hawsers and Warps	"
Wales	"	Rudder	efficient	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper	Fe 4 1/2 mm When put on 1869			
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways good					

Re-lashed head knee, wedged up Port Haul pipe. Caulked Woodends from 70 ft upwards Patched 100 ft metal. She is as far as seen in good condition and entitled to remain as classed. 13. A. I. Samuel Presious

Committee's Minute 24<sup>th</sup> May 1870  
 Character assigned 13 1 WWT

Certificate (if required)

LON655-0355



La Hague  
Coutances



© 2021

Lloyd's Register  
Foundation