

ANNUAL SURVEYS.

30878

No. 167 Survey held at London Date 2nd - 23rd May 1870
 on the Ship "Agamemnon" Master R. Marsden
 Tonnage 1431 Built at London When built 1855
 By whom built Green Owners R. & H. Green
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Green's upper dry dock

Last Survey, No. 30270 Port of Lon. Classed Rest. 63-7 yrs
H.T. 69.
7.69.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>4. Met.</u> When put on <u>1869.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Topsides caulked from diagonal doubling to inside of
waterway. Yellow metal coated with Peacock's Composition.
Is now in good and efficient condition, and fit in my opinion
to remain as classed - Rest. 63-7 yrs.

Committee's Minute 27th May 1870.

Character assigned Rest. 7 A 1 W.H.

J. H. Eastlake.

Certificate (if required).

No. 44 Survey held at London Date 6th - 23rd May 1870
 on the Ship "Queen of Nations" Master A. Donald
 Tonnage 846 Built at Aberdeen When built 1861
 By whom built Hood Owners Thompson Jun.
 Port belonging to Aberdeen Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Green's Lower Dry Dock.

Last Survey, No. 29426 Port of Lon. Classed 14 A 1.
H.T. 68.
8, 68.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>T. & G. M.</u> When put on <u>1868.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Yellow metal patched and coated with Peacock's Composition.
Is now in good and efficient condition, and fit in my opinion
to remain as classed - 14 A 1.

Committee's Minute 27th May 1870.

Character assigned 14 A 1 W.H.

J. H. Eastlake.

Certificate (if required).

101655-0356