

30881

REPORT of SURVEY for REPAIRS.

No. 30084 Survey held at London Date, first Survey 9th February Last Survey 21st February 18 70
on the Ship "Pembroke" Master N. Wilkinson
Tonnage 721 built at Pembroke Dock When built 1864, 1 mo.
By whom built Allan Owners Jenkins &c.
Port belonging to London Destined Voyage India
If Surveyed Afloat or in Dry Dock Lincoln Dry Dock and East India Dock.
Survey, No. 30084 Port Lon Classed 10.A.1
(HT-69) 2-69
IRS, &c. Now done

The yellow metal sheathing stripped off the bottom; the Rudder unhung, and
its bolts through the braces renewed.
The Vessel caulked from keel to gunwale, and resheathed with yellow-
metal on felt.

Condition of the

ays	Good when seen	Treenails	Good when seen	Windlass and Capstan	Good and efficient
Deck Beams & Fastenings		Breasthooks and Stemson		Pumps	
Deck Beams & Fastenings		Transoms, Pointers, and Crutches		Boats	
Decks		Timbers of the Frame at the openings		Masts, Yards, &c.	
Keelsons		Ditto Ditto at other places		Condition, how ascertained <u>from the Deck & Engine</u>	
Clamps and Shelves		Keelsons		Sails	
Ceiling		Clamps and Shelves		Anchors No. of <u>3 B. 1 S. 2 K</u>	
Rudder		Ceiling		Cables	
Copper <u>Yellow metal</u> When put on <u>now</u>		Rudder		Hawsers and Warps	
Caulking of		Copper <u>Yellow metal</u> When put on <u>now</u>		Standing & Running Rigging	
Bottom) and Counter	Bottom, Deck, & Waterways <u>good when tested</u>				
Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u>			

Observations and Opinion,
The vessel is in good and efficient condition, and in my opinion, fit to remain
classed (vms): 10.A.1 -

Amount of Entry Fee.....£ - : - : is received by me,
Special..... 1 : 1 :
Certificate (if required) : 5 :
Committee's Minute 31st May 18 70
Master assigned 10th June

Wm J. Bone