

ANNUAL SURVEYS.

30949

Rev 2/1/70

No. 352 Survey held at London Date 30th May - 29th June 1870
 on the Ship "Alnwick Castle" Master De Carteret
 Tonnage 1087 Built at Sunderland When built 1856
 By whom built — Owners H. Green
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock

Last Survey, No. 30098 Port of Lon. Classed 13 A 1.
Cont. 69-9.
4, 69.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>2 1/2</u> M. When put on <u>189.</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined.
Yellow metal patched, and coated with Peacock's Composition. Recaulked
butts of top-riders. New fore-castle deck of 3" Dantie Fir.
Is now in good and efficient condition, and fit in my opinion to
remain as classed - Continued 189-9 yrs.

Committee's Minute 5th July 1870
 Character assigned Cont 9 A 1
J. H. Eastlake;

Certificate (if required).

No. 126 Survey held at London Date 29th June - 1st July 1870
 on the Ship "The Lord Warden" Master J. Smith
 Tonnage 1237 Built at Sunderland When built 1862
 By whom built Pile Owners R. Green
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock

Last Survey, No. 29465 Port of Lon. Classed 13 A 1.
H.T. 68.
9, 68.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>2 1/2</u> M. When put on <u>188.</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined.
Yellow metal patched, and coated with Peacock's Composition.
Recaulked butts in top-riders and deck, also the waterway beams.
Is now in good and efficient condition, and fit in my opinion
to remain as classed - 13 A 1.

Committee's Minute 5th July 1870
 Character assigned 13 A 1
J. H. Eastlake.

Certificate (if required).