

Change of Owners.

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 32 No. 1126 Survey held at London Date, first Survey 24th June Last Survey 8th July 1870
on the Ship "Xile" Master H. W. Crippin
Tonnage 1126 built at London When built 1850
By whom built — Owners Alfred Mumford
Port belonging to London Destined Voyage Gibraltar
If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock.
Last Survey, No. 28400 Port London. Classed 12 A1.
Cont. 62-8.
6, 67.

REPAIRS, &c.

Vessel recaulked from keel to top of wales, and bottom retailed on felt.

Present Condition of the

Decks		Treenails		x Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	Good	Timbers of the Frame at the openings	Good	Masts, Yards, &c.	Good and
Lower Deck Beams & Fastenings	where	Ditto Ditto at other places	where	Condition, how ascertained	complete
Planksheers	where	Keelsons	where	Sails	where run.
Sheerstrakes	run.	Clamps and Shelves	run.	Anchors No. of	
Topsides	run.	Ceiling	run.	Cables	
Wales		Rudder	run.	Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>4. 11. m. 7.</u> When put on <u>Now.</u>		Standing & Running Rigging	
Engine Room Skylights		Caulking of		Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	Good where told	Hatches	Good
Scuppers	Good				

General Observations and Opinion,

Is now in good and efficient condition, and fit in my opinion to remain as classed —
Continued 62-8 yrs.

J. H. Eastlake,

The Amount of Entry Fee.....£ 1 : - : is received by me,
Special..... 1 : 1 :
Certificate (if required) : : }

Committee's Minute 15th July 1870

Character assigned Cont. 8 A 1

record WMA