

ANNUAL SURVEYS.

3098

Recd 20/7/70

No. 202 Survey held at London Date 4th June - 15th July 18 70
 on the Barque "Phaeton" Master J. Milligan
 Tonnage 416 Built at Whitehaven When built 1859
 By whom built Kennedy Owners W. Turner
 Port belonging to Dumfries Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock Lower Globe Dry Dock.

Last Survey, No. 29786 Port of Lon. Classed 13 A1.
1, 69.

Windlass stripped - Report 29786.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>2 1/4</u> M. When put on <u>1869.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Bottom sighted, and metal patched. Topsides caulked.
Is now in good and efficient condition, and fit in my opinion
to remain as classed - 13 A1.

J. H. Haslake.

Committee's Minute 22nd July 1870

Character assigned 13 A1

Certificate (if required).

No. 40 Survey held at London Date 13th July 18 70
 on the Barque "Eastern Chief" Master Swell
 Tonnage 401 Built at Harrington When built 1861
 By whom built Liverpool Owners J. Martin
 Port belonging to Liverpool Destined Voyage Yokohama
 If Surveyed Afloat or in Dry Dock Britannia Dock & East India Dock

Last Survey, No. 20757 Port of Liv. Classed 14 A1
5.67

Windlass stripped & renewed 1867

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>T. & M.</u> When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

The bills for metalting seen, the bottom sighted and metal
repaired where required. Is now in good and efficient condition
and eligible in my opinion to remain as classed 14 A1

Committee's Minute 22nd July 1870

Character assigned 14 A1

Certificate (if required).

Wm. H. Brown
 Lloyd's Register
 Foundation