

REPORT of SURVEY for REPAIRS.

31012

No. in Reg. Book. 48 No. 1094 Survey held at London Date, first Survey 4th July Last Survey 27th July 1870
 on the Ship St Lawrence Master J. Wilcox
 Tonnage 1094 built at Newcastle When built 1861
 By whom built Smith Owners J. Southern
 Port belonging to London Newcastle Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Greens upper dock & East India Docks
 Last Survey, No. 29337 Port Lon. Classed 14. A. 1. H. T. in 1868
 7. 68

REPAIRS, &c.

Stripped off the whole of the Yellow Metal Sheathing
 Caulked from Keel to Gunwale. Hung her.
 Resheathed with Yellow Metal.

Present Condition of the

Decks	<u>good</u>	Treenails	<u>where seen</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	<u>firm</u>	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	<u>from the Deck</u>
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors	No. of <u>3 V 1 S. 2 K</u>
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	<u>efficient</u>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<u>Yellow Metal</u>	<u>When put on now</u>	Standing & Running Rigging	"
Engine Room Skylights	"	Caulking of	<u>good</u>	"	Cargo and Main Hatchways	<u>good</u>
General Observations and Opinion,	"	Bottom, Deck, & Waterways	<u>where tested</u>	<u>good</u>	Hatches	<u>good</u>

Coal Bunker, Openings, Lids, &c. Scuppers good

She appears to be in good condition, and is in my
 opinion entitled to remain as class'd 14. A. 1.
 Samuel Presious

The Amount of Entry Fee.....£ - : - : is received by me,

Special..... / : / :

Certificate (if required) : :

Committee's Minute

Character assigned



© 2021

Lloyd's Register
 Foundation

LONGS5-0441

St Lawrence

REPORT OF THE COMMITTEE OF THE



© 2021

Lloyd's Register
Foundation