

ANNUAL SURVEYS.

31049

Survey held at London Date 13th Aug^y 20th 1870
 Ship Dartmouth Master Elsden
 No. 933 Built at Dundee When built 1859
 By whom built Stephens Owners Somes Brs
 Port belonging to London Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock Canal dry dock

Survey, No. 30240 Port of London. Classed 14. A. 1. C. P.
69

Condition of the

<u>good</u>	Treenails <u>where seen</u>	<u>good</u>	Windlass and Capstan <u>in good order</u>
"	Breasthooks and Stemson	"	Pumps
"	Transoms, Pointers, and Crutches	"	Boats
Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame at the Openings	"	Masts, Yards, &c.
Deck Beams & Fastenings	Ditto ditto at other places	"	Sails
Planksheers	Keelsons	"	Anchors No. of <u>3 & 1 S. 2 K</u>
Sheerstrakes	Clamps and Shelves	"	Cables
Topsides	Ceiling	"	Hawsers and Warps
Wales	Rudder <u>efficient</u>	"	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>for 14 mtl</u> When put on <u>1869</u>		
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <u>good</u>		

As far as seen She is in good condition and I am of
 opinion is entitled to remain as class'd 14. A. 1.
 Samuel Presins

Committee's Minute 23rd August 1870.

Character assigned 14 A 1 Mtl

Certificate (if required).

No. 439 Survey held at London Date 17th Aug^y 20th 1870
 on the Barque Anazi Master John Hillman
 Tonnage 468 Built at Portsmouth When built 1865
 By whom built Turnbull Owners J. Fleming
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Wigram's dry dock

Last Survey, No. 29510 Port of Lon. Classed 16. A. 1.
9. 68

The present Condition of the

<u>good</u>	Treenails <u>Bolts where seen</u>	<u>good</u>	Windlass and Capstan <u>in good order</u>
Decks	Breasthooks and Stemson	"	Pumps
Waterways	Transoms, Pointers, and Crutches	"	Boats
Comings	Timbers of the Frame at the Openings	"	Masts, Yards, &c.
Upper Deck Beams & Fastenings <u>firm</u>	Ditto ditto at other places	"	Sails
Lower Deck Beams & Fastenings	Keelsons	"	Anchors No. of <u>3 & 1 S. 2 K</u>
Planksheers	Clamps and Shelves	"	Cables
Sheerstrakes	Ceiling	"	Hawsers and Warps
Topsides	Rudder <u>efficient</u>	"	Standing & Running Rigging
Wales	Copper <u>for 14 mtl</u> When put on <u>1868</u>		
Plank (Bottom) and Counter	Caulking of Bottom, Deck, and Waterways <u>good</u>		
General Observations and Opinion,			

Improved the Steering apparatus. Sighted the yellow metal
 paid the bottom or sheathing with "Peacocks Rust Corrosive"

She appears to be in good condition and is in my
 opinion entitled to remain as class'd 16. A. 1.

Committee's Minute 23rd August 1870.

Character assigned 16 A 1

Certificate (if required).