

REPORT of SURVEY for REPAIRS.

31090

No. 1362 Survey held at London Date, first Survey 15th Augst 70 Last Survey 19th Augst 70
 on the bark "Gemini" Master C. Pallot
 Tonnage 426 built at Jersey When built 1864
 By whom built L. Peseante Owners J. Delands
 Port belonging to Jersey Destined Voyage not fixed
 If Surveyed Afloat or in Dry Dock Ratchiffe Dry Dock

Last Survey, No. 1362 Port Jersey Classed 10 A 1
 REPAIRS, &c. cf. H.I. 68 9.68

Shipped Yellow Metal Sheathing; caulked from keel to middle of wales. and resheathed bottom with Yellow Metal in felt.

Present Condition of the		
Decks	Treenails	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson	Pumps <u>—</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>—</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>—</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>seen from the deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>2</u> <u>good</u>
Topsides	Ceiling	Cables <u>and</u>
Wales	Rudder	Hawsers and Warps <u>insufficient</u>
Plank (Bottom) and Counter	Copper <u>4 1/2 in</u> When put on <u>new</u>	Standing & Running Rigging <u>—</u>
Engine Room Skylights	Caulking of <u>3 1/2 in</u>	Cargo and Main Hatchways <u>good</u>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>3 1/2 in</u>	Hatches <u>good</u>
General Observations and Opinion,	Scuppers <u>good</u>	

Is now in good and efficient condition and in our opinion eligible to remain as classed 10 A 1.

The Amount of Entry Fee.....£ : : is received by me,
 Special..... / : /
 Certificate (if required) : 5 :

Committee's Minute 9th September 1870
 Character assigned 10 A 1